

Model	Full Step Angle	Holding Torque (Ncm)	Current/ Phase (A)	Resistance/ Winding (Ω)	Inductance/ Winding (mH)	Voltage DC (V)	Torque/ Speed
A = Single B = Double Shaft							
SECM 569 - T 1.4 A SECM 569 - T 1.4 B	0.72°	166	1.40	1.8	7.5	2.5	Ⓔ
SECM 569 - T 2.8 A SECM 569 - T 2.8 B	0.72°	166	2.80	0.65	2.5	1.8	Ⓕ
Number of Leads	Weight (Kg)		Size Length (mm)			Rotor Inertia (gcm ²)	
10	1.2		60x60x86.5			440	

